

| OK-HKE | | Maintenance summary Part I (List of life limited A/C parts) | | | | | | | | | | Effective Date: | | | 17.04.2013 | | |
|---------------------|--|---|-----|-----------|------------------|-------|--------|--------|-------------------------|------------|--------|-----------------|------------|--------|----------------------|-----------------|--------------------|
| | | Type TU206G | | | S/N U20603877 | | | | | | | Year | | | Total time 6736,3 | Cycles 2 044 | Date 12.08.2016 |
| Item | Component / Part | P/N / Model | S/N | Reference | Action due | Limit | | | Performed / Instalation | | | Next Due | | | Remaining | | |
| | | | | | | Hours | Months | Cycles | Hours | Date | Cycles | Hours | Date | Cycles | Hours | Days | Cycles |
| Schedule Inspection | | | | | | | | | | | | | | | | | |
| 1 | Airworthiness Review Certificate | | | | Issue | - | 12 | - | 6374,8 | 03.03.2011 | - | - | 02.03.2012 | - | - | -1 624 | - |
| 2 | Avionic inspections (Airspeed/Vario indicator) | | | | | - | 24 | - | 6100,0 | 02.02.09 | - | - | 02.02.2011 | - | - | -2 018 | - |
| 3 | Avionic inspections Altimeter check | | | | | - | 24 | - | 6474,1 | 10.11.11 | 1927 | - | 09.11.2013 | - | - | -1 007 | - |
| 4 | Avionic inspections Pitotstatic leak check | | | | | - | 24 | - | 6474,1 | 10.11.11 | 1927 | - | 09.11.2013 | - | - | -1 007 | - |
| 5 | Avionic inspections XPNDR check | | | | | - | 24 | - | 6474,1 | 10.11.11 | 1927 | - | 09.11.2013 | - | - | -1 007 | - |
| 6 | Battery check + electrolyte level | | | | | 100 | 3 | - | 6474,1 | 10.11.11 | 1927 | 6574,1 | 09.02.2012 | - | -162,2 | -1 646 | - |
| 7 | Engine oil | | | | | 50 | 6 | - | 6474,1 | 10.11.11 | 1927 | 6524,1 | 10.05.2012 | - | -212,2 | -1 555 | - |
| 8 | Annual inspection | | | | | - | 12 | - | 6474,1 | 10.11.11 | 1927 | - | 09.11.2012 | - | - | -1 372 | - |
| 9 | 1 Year inspection | | | | | - | 12 | - | 6474,1 | 10.11.11 | 1927 | - | 09.11.2012 | - | - | -1 372 | - |
| 10 | 1 Year / 400 Hour inspection | | | | | 400 | 12 | - | 6474,1 | 10.11.11 | 1927 | 6874,1 | 09.11.2012 | - | 137,8 | -1 372 | - |
| 11 | 50 hrs inspection | | | | | 50 | - | - | 6474,1 | 10.11.11 | 1927 | 6524,1 | - | - | -212,2 | - | - |
| 12 | 100 hrs inspection | | | | | 100 | - | - | 6474,1 | 10.11.11 | 1927 | 6574,1 | - | - | -162,2 | - | - |
| 13 | 200 hrs inspection | | | | | 200 | - | - | 6474,1 | 10.11.11 | 1927 | 6674,1 | - | - | -62,2 | - | - |
| 14 | Fire extinguisher weighting | | | | | - | 12 | - | 6474,1 | 10.11.11 | 1927 | - | 09.11.2012 | - | - | -1 372 | - |
| 15 | Compass swing | | | | | - | 12 | - | 6474,1 | 10.11.11 | 1927 | - | 09.11.2012 | - | - | -1 372 | - |
| 16 | Item A | | | | | 500 | - | - | 6474,1 | 10.11.11 | 1927 | 6974,1 | - | - | 237,8 | - | - |
| 17 | Item B | | | | | - | 60 | - | 6242,0 | 17.02.10 | - | - | 16.02.2015 | - | - | -543 | - |
| 18 | Item C | | | | | 600 | 12 | - | 6474,1 | 10.11.11 | 1927 | 7074,1 | 09.11.2012 | - | 337,8 | -1 372 | - |
| 19 | Item D | | | | | 1000 | 36 | - | 6242,0 | 17.02.10 | - | 7242,0 | 16.02.2013 | - | 505,7 | -1 273 | - |
| 20 | Engine air filter replacement | | | | | 500 | 36 | - | 6242,0 | 17.02.10 | - | 6742,0 | 16.02.2013 | - | 5,7 | -1 273 | - |
| 21 | Item R | | | | | 100 | - | - | 6474,1 | 10.11.11 | 1927 | 6574,1 | - | - | -162,2 | - | - |
| 22 | Vacuum pump replacement | | | | | 500 | - | - | 6242,0 | 17.02.10 | - | 6742,0 | - | - | 5,7 | - | - |
| 23 | Vacuum pump drive coupling | | | | | - | 72 | - | 6242,0 | 17.02.10 | - | - | 16.02.2016 | - | - | -178 | - |
| 24 | Item I | | | | | 500 | - | - | 6242,0 | 17.02.10 | - | 6742,0 | - | - | 5,7 | - | - |
| 25 | Item Q | | | | | 500 | - | - | 6342,0 | 04.10.10 | - | 6842,0 | - | - | 105,7 | - | - |
| 26 | Item M | | | | | 1000 | - | - | 6093,0 | 17.10.08 | - | 7093,0 | - | - | 356,7 | - | - |
| 27 | Item U | | | | | - | 120 | - | 6093,0 | 17.10.08 | - | - | 15.10.2018 | - | - | 794 | - |
| 28 | Restraint assy COPILOT replacement | | | | | - | 120 | - | 6374,8 | 02.03.11 | - | - | 27.02.2021 | - | - | 1 660 | - |
| 29 | Restraint assy PILOT replacement | | | | | - | 120 | - | 6374,8 | 02.03.11 | - | - | 27.02.2021 | - | - | 1 660 | - |
| 30 | Restraint assy LH PAX replacement | | | | | - | 120 | - | - | - | - | - | - | - | - | - | - |
| 31 | IFRequipment check | | | | | - | 12 | - | - | - | - | - | - | - | - | - | - |
| 32 | Item T | | | | | - | 12 | - | - | - | - | - | - | - | - | - | - |
| 33 | Item K | | | | | 500 | - | - | - | - | - | - | - | - | - | - | - |
| 34 | Landing light switch replacement | PN:TA201TW-B | | | | - | 60 | - | - | - | - | - | - | - | - | - | - |
| 35 | STBY vacuum pump replacement | | | | | 50 | 120 | - | - | - | - | - | - | - | - | - | - |
| 36 | Item V | | | | | 300 | - | - | - | - | - | - | - | - | - | - | - |

| | | | | | | | | | | | | | | | | | |
|----|---|--|--|--|--|------|-----|---|---|---|---|---|---|---|---|---|---|
| 37 | Pitot and static system hoses replacement | | | | | - | 120 | - | - | - | - | - | - | - | - | - | - |
| 38 | Restraint assy RH PAX replacement | | | | | - | 120 | - | - | - | - | - | - | - | - | - | - |
| 39 | Item O | | | | | 1000 | - | - | - | - | - | - | - | - | - | - | - |
| 40 | Item G | | | | | 500 | - | - | - | - | - | - | - | - | - | - | - |
| 41 | Item L | | | | | - | 60 | - | - | - | - | - | - | - | - | - | - |



