

OK-EKS		Maintenance summary Part I (List of life limited A/C parts)										Effective Date:		22.10.2015					
		Type PA-31-350			S/N 31-8152101									Total time 7632,5	Cycles -	Date 12.08.2016			
Item	Component / Part	P/N / Model	S/N	Reference	Action due	Limit			Performed / Instalation			Next Due			Remaining				
						Hours	Months	Cycles	Hours	Date	Cycles	Hours	Date	Cycles	Hours	Days	Cycles		
Airframe																			
1	Airworthineess reiew certificate				Issue	-	12	-	7606,4	06.03.2015	-	-	05.03.2016	-	-	-160	-		
2	ELT battery				Life limit	-	60	-	-	18.05.10	-	-	17.05.2015	-	-	-453	-		
3	Propeller air press and Battery compt check				Inspection	50	1	-	7632,5	22.04.15	-	7682,5	22.05.2015	-	50,0	-448	-		
4	Hydr. & Brake Hoses Set LH + RH				Life limit	-	60	-	-	01.07.10	-	-	30.06.2015	-	-	-409	-		
5	Fire extinguisher weighting				Life limit	-	12	-	7561,4	02.10.14	-	-	02.10.2015	-	-	-315	-		
6	Annual Inspection				Inspection	-	12	-	7561,4	02.10.14	-	-	02.10.2015	-	-	-315	-		
7	Compass swing				Avionic	-	12	-	7561,4	02.10.14	-	-	02.10.2015	-	-	-315	-		
8	IFRequipment check				Avionic	-	12	-	7562,8	07.10.14	-	-	07.10.2015	-	-	-310	-		
9	Altimeter check				Avionic	-	24	-	7461,2	10.10.13	0	-	10.10.2015	-	-	-307	-		
10	Pitotstatic leak check				Avionic	-	24	-	7461,2	10.10.13	0	-	10.10.2015	-	-	-307	-		
11	Fire extinguisher OH				OH	-	72	-	0,0	31.10.09	0	-	30.10.2015	-	-	-287	-		
12	50 Hrs Inspection				Inspection	50	-	-	7606,4	24.03.15	-	7656,4	-	-	23,9	-	-		
13	Life Limit Vac. Relief Valve Filters				Life limit	200	-	-	7461,2	-	-	7661,2	-	-	28,7	-	-		
14	Roder Prazision STC Ro - 1223 camera instl. inspection				Inspection	100	-	-	7561,4	02.10.14	-	7661,4	-	-	28,9	-	-		
15	100 Hrs Inspection				Inspection	100	-	-	7561,4	02.10.14	-	7661,4	-	-	28,9	-	-		
16	Oxygen system inspection				Inspection	300	-	-	7461,2	10.10.13	-	7761,2	-	-	128,7	-	-		
17	First aid kit expiration check				Check	-	24	-	7561,4	02.10.14	-	-	01.10.2016	-	-	50	-		
18	Pneumatic pressure inline filter	PN:1 J4-6			Replacement	500	-	-	7412,8	01.07.10	-	7912,8	-	-	280,3	-	-		
19	500 Hrs Inspection				Inspection	500	-	-	7450,2	02.04.12	-	7950,2	-	-	317,7	-	-		
20	1000 Hrs Inspection				Inspection	1000	-	-	7027,9	27.06.08	-	8027,9	-	-	395,4	-	-		
21	Aircraft weighing check					-	48	-	7461,2	10.10.13	-	-	09.10.2017	-	-	423	-		
22	Turbocharger V-BAND clamps				Replacement	1000	-	-	7234,7	18.05.09	-	8234,7	-	-	602,2	-	-		
23	Elevator bungee spring and link replacement				Replacement	1000	-	-	7412,8	01.07.10	-	8412,8	-	-	780,3	-	-		
24	Overhaul Limit Cabin Heater Airframe CD14048-1-1455				OH	1500	-	-	6926,4	17.01.08	-	8426,4	-	-	793,9	-	-		
25	Oxygen pressure regulator				OH	-	60	-	-	21.05.13	-	-	20.05.2018	-	-	646	-		
26	Life Limit RH Inboard Hinge RH Aileron spar				Life limit	1000	-	-	7461,2	-	-	8461,2	-	-	828,7	-	-		
27	Life Limit LH Inboard Hinge LH Aileron spar				Life limit	1000	-	-	7461,2	-	-	8461,2	-	-	828,7	-	-		
28	Hydraulic hoses				Life limit	-	120	-	-	21.05.13	-	-	19.05.2023	-	-	2 471	-		
29	Airframe fuel hoses				Life limit	-	120	-	-	21.05.13	-	-	19.05.2023	-	-	2 471	-		
30	Oxygen Bottle P6084-38				Life limit	-	288	-	-	20.05.04	-	-	14.05.2028	-	-	4 293	-		
31	Inboard aileron spar hinge			Replace iaw AD 96-21-03	Replacement	1000	-	-				1000,0	-	-	-6632,5	-	-		
32	Fuel cell inspection				Inspection	-	14	-				-	28.02.1901	-	-	-42 168	-		
33	XPNDR check				Avionic	-	24	-				-	30.12.1901	-	-	-41 864	-		
34	LDG selector cable				Replacement	4000	120	-				4000,0	28.12.1909	-	-3632,5	-38 944	-		
35	Engine and nacelle area pneumatic hoses				Life limit	1000	96	-				1000,0	29.12.1907	-	-6632,5	-39 674	-		
Engine 1																			
1	Rubber engine mount kit	J9613-29			Life limit	500	-	-	7234,7	06.05.09	-	7734,7	-	-	102,2	-	-		
2	Propeller governor	F-6-24	D3809TJ		OH	2000	-	-	6543,9	01.10.04	-	8543,9	-	-	911,4	-	-		
3	Hydraulic pump	1213HBG310	22711		OH	1800	-	-	6543,9	01.10.04	-	8343,9	-	-	711,4	-	-		

4	Injector	RSA-10ED1	46053		OH	1800	-	-	7234,7	06.05.09	-	9034,7	-	-	1402,2	-	-
5	Alternator	ALU8521R	J012573		OH	1800	-	-	7234,7	06.05.09	-	9034,7	-	-	1402,2	-	-
6	Starter	MHB4016R	I092438		OH	1800	-	-	7234,7	06.05.09	-	9034,7	-	-	1402,2	-	-
7	Turbocharger	409170-0001	MBL00077		OH	1800	-	-	7234,7	06.05.09	-	9034,7	-	-	1402,2	-	-
8	Fuel Pump	RG9080J4A/M	MAN070FP		OH	1800	-	-	7234,7	06.05.09	-	9034,7	-	-	1402,2	-	-
9	Engine	O-540-J2BD	RL-3876-61A		OH	1800	144	-	7234,7	06.05.09	-	9034,7	03.05.2021	-	1402,2	1 725	-
10	Magneto	D6LN-3200	G09AA090		OH	1800	-	-	7461,2	10.10.13	-	9261,2	-	-	1628,7	-	-
11	Electric fuel pump	42113-5			OH	2000	-	-	7461,2	10.10.13	-	9461,2	-	-	1828,7	-	-
12	50Hrs				Inspection	50	-	-	7606,4	24.03.15	-	7656,4	-	-	23,9	-	-
13	100 hrs inspection				Inspection	100	-	-	7561,4	02.10.14	-	7661,4	-	-	28,9	-	-
14	LSB 388 Valve seats					400	-	-	7561,4	02.10.14	-	7961,4	-	-	328,9	-	-
15	400 hrs inspection				Inspection	400	-	-	7561,4	02.10.14	-	7961,4	-	-	328,9	-	-
Engine 1																	
1	50Hrs				Inspection	50	-	-	7606,4	24.03.15	-	7656,4	-	-	23,9	-	-
2	100 hrs inspection				Inspection	100	-	-	7561,4	02.10.14	-	7661,4	-	-	28,9	-	-
3	Hydraulic pump	1213HBG310	OF9-0143		OH	1800	-	-	6543,9	01.10.04	-	8343,9	-	-	711,4	-	-
4	Propeller governor	F-6-24	D1917TJ		OH	2000	-	-	6543,9	01.10.04	-	8543,9	-	-	911,4	-	-
5	Engine	O-540-J2BD	RL-2002-68A		OH	1800	144	-	7413,8	17.11.10		9213,8	14.11.2022	-	1581,3	2 285	-
6	Electric fuel pump	42113-5			OH	2000	-	-	7461,2	10.10.13	-	9461,2	-	-	1828,7	-	-
7	400 hrs inspection				Inspection	400											
8																	
AD/SB																	
1	AD 2003-24-07	Rudder torque tube and rib corrosion				-	12	-	7561,4	02.10.14	-	-	02.10.2015	-	-	-315	-
2	AD 98-08-18	Elevator bungee spring				100	-	-	7561,4	02.10.14	-	7661,4	-	-	28,9	-	-
3	AD 2009-13-06	Nose baggage door lubrication				100	-	-	7561,4	02.10.14	-	7661,4	-	-	28,9	-	-
4	AD 99-12-05	Elevator spar				100	-	-	7561,4	02.10.14	-	7661,4	-	-	28,9	-	-
5	AD 2000-25-01	MLG inboard door hinge cracks				2000	-	-	6497,2	05.05.04	-	8497,2	-	-	864,7	-	-
6	AD 2001-06-01	Detect damage to elevator structure				100	-	-			-	100,0	-	-	-7532,5	-	-
7	AD 96-21-03	Inb aileron spar hinge insp.				100	-	-			-	100,0	-	-	-7532,5	-	-
8	LSB 480 Oil and filter change					50	4	-	7606,4	24.03.15	-	7656,4	23.07.2015	-	23,9	-385	-
9	AD 2008-14-07		Prevent fail of fuel inj lines LSB342//EASaus AD 2011-26-04			100	12	-	7561,4	02.10.14	-	7661,4	02.10.2015	-	28,9	-315	-
10	AD 2009-03-02	Hex plug				50	-	-			-	50,0	-	-	-7582,5	-	-
11	LSB 388 Valve seats					400	-	-	7561,4	02.10.14	-						

